

Vehicle Inspection Checklist

Date & Time

21/09/2021 10:00 AM

	Fill in the details below		
Dealer Name	TIAN SIANG PREMIUM AUTO		
Dealer Location	Jln.Kuala Kangsar, Ipoh		
Make/Model	Mercedes Benz C200 Coupe 2.0		
Colour	Dark Grey		
Chassis/Number Plate	VGN9638		
Year Make	2016		
Mileage	134820 kms		

Engine

	Pass
Engine Diagnosis	$\overline{\checkmark}$
Engine Start Properly	$\overline{\checkmark}$
Engine Idles Properly	$\overline{\checkmark}$
Remote Start System	$\overline{\checkmark}$
Engine Noise Normal	$\overline{\checkmark}$
Engine Oil/Oil Filter	$\overline{\checkmark}$
Throttle Condition	$\overline{\checkmark}$
Coolant	$\overline{\checkmark}$
Oil Leakage	$\overline{\checkmark}$
Exhaust Emission	$\overline{\checkmark}$

Transmission

	Pass
Transmission Diagnosis	$\overline{\checkmark}$
Gear Shift Quality	$\overline{\checkmark}$
Slippage/Jerking	$\overline{\checkmark}$

Cooling System

	Pass
Diagnosis	$\overline{\checkmark}$
Coolant Level	$\overline{\checkmark}$
Cooling Fans & Motors	$\overline{\checkmark}$

Body/Chassis

	Pass
Free From Major Accident/Body Cut & Joint	$\overline{\checkmark}$
Free From Flood Damage	$\overline{\checkmark}$
Genuine Chassis & Engine No. (if applicable)	$\overline{\checkmark}$

Other Electricals

	Pass
Electrical Diagnosis	$\overline{\checkmark}$
Starter Operation	$\overline{\checkmark}$
Ignition System	$\overline{\checkmark}$
Battery	
Alternator Output	$\overline{\checkmark}$
Fuel System Diagnosis	$\overline{\checkmark}$
Braking System Diagnosis	$\overline{\checkmark}$
Air-conditioning System Diagnosis	$\overline{\checkmark}$
Steering Mechanism Diagnosis	$\overline{\checkmark}$

Inspection Notes

	Section	Item	Notes
1	Body/Chasis.	Front bumper	replaced.
2	Others	Battery	weak - dealer to replace.
3	Others	Turn signal lamp on front left mirror	malfunction.
4	Others	Turn signal lamp on front right mirror	malfunction.
5			

Inspector Name

SAG-Chin

Inspector Signature

Collaboration between Carlist.my & WARRANTY SMARTH



