

Vehicle Inspection Checklist

Date & Time

16/04/2021 1:30 PM

| | Fill in the details below |
|----------------------|-----------------------------|
| Dealer Name | NL AUTOMOBILE SDN BHD |
| Dealer Location | Klang, Selangor |
| Make/Model | Land Rover Evoque 2.0 |
| Colour | Red |
| Chassis/Number Plate | SALVA2AG6FH968973 / WA9867S |
| Year Make | 2014 |
| Mileage | 77101 kms |

Engine

| | Pass |
|-----------------------|-------------------------|
| Engine Diagnosis | $\overline{\checkmark}$ |
| Engine Start Properly | $\overline{\checkmark}$ |
| Engine Idles Properly | $\overline{\checkmark}$ |
| Remote Start System | $\overline{\checkmark}$ |
| Engine Noise Normal | $\overline{\checkmark}$ |
| Engine Oil/Oil Filter | $\overline{\checkmark}$ |
| Throttle Condition | $\overline{\checkmark}$ |
| Coolant | $\overline{\checkmark}$ |
| Oil Leakage | $\overline{\checkmark}$ |
| Exhaust Emission | $\overline{\checkmark}$ |

Transmission

| | Pass |
|------------------------|-------------------------|
| Transmission Diagnosis | $\overline{\checkmark}$ |
| Gear Shift Quality | $\overline{\checkmark}$ |
| Slippage/Jerking | $\overline{\checkmark}$ |

Cooling System

| | Pass |
|-----------------------|-------------------------|
| Diagnosis | $\overline{\checkmark}$ |
| Coolant Level | $\overline{\checkmark}$ |
| Cooling Fans & Motors | $\overline{\checkmark}$ |

Body/Chassis

| | Pass |
|--|-------------------------|
| Free From Major Accident/Body Cut & Joint | $\overline{\checkmark}$ |
| Free From Flood Damage | $\overline{\checkmark}$ |
| Genuine Chassis & Engine No. (if applicable) | $\overline{\checkmark}$ |

Other Electricals

| | Pass |
|-----------------------------------|-------------------------|
| Electrical Diagnosis | $\overline{\checkmark}$ |
| Starter Operation | $\overline{\checkmark}$ |
| Ignition System | $\overline{\checkmark}$ |
| Battery | $\overline{\checkmark}$ |
| Alternator Output | $\overline{\checkmark}$ |
| Fuel System Diagnosis | $\overline{\checkmark}$ |
| Braking System Diagnosis | $\overline{\checkmark}$ |
| Air-conditioning System Diagnosis | $\overline{\checkmark}$ |
| Steering Mechanism Diagnosis | $\overline{\checkmark}$ |

Inspector Name

Redzwan

Inspector Signature



Collaboration between Carlist.my & WARRANTY SMART



