



# Vehicle Inspection Checklist

## Date & Time

15/10/2021

3:30 PM

	Fill in the details below
Dealer Name	TOP CAR AUTOMOBILE
Dealer Location	Sungai Petani
Make/Model	Toyota Corolla Altis 2.0V Sedan
Colour	White
Chassis/Number Plate	MR053RFH304000173 / W5558S
Year Make	2014
Mileage	80007 kms

## Engine

	Pass
Engine Diagnosis	✓
Engine Start Properly	✓
Engine Idles Properly	✓
Remote Start System	✓
Engine Noise Normal	✓
Engine Oil/Oil Filter	✓
Throttle Condition	✓
Coolant	✓
Oil Leakage	✓
Exhaust Emission	✓

## Transmission

	Pass
Transmission Diagnosis	✓
Gear Shift Quality	✓
Slippage/Jerking	✓

## Cooling System

	Pass
Diagnosis	✓
Coolant Level	✓
Cooling Fans & Motors	✓

## Body/Chassis

	Pass
Free From Major Accident/Body Cut & Joint	✓
Free From Flood Damage	✓
Genuine Chassis & Engine No. (if applicable)	✓

## Other Electricals

	Pass
Electrical Diagnosis	✓
Starter Operation	✓
Ignition System	✓
Battery	✓
Alternator Output	✓
Fuel System Diagnosis	✓
Braking System Diagnosis	✓
Air-conditioning System Diagnosis	
Steering Mechanism Diagnosis	✓

## Inspection Notes

	Section	Item	Notes
1	Other Electricals.	Air-conditioning system OBD diagnosis.	Fault code B1423 – Open in Pressure Sensor Circuit / Abnormal Refrigerant Pressure.
2			
3			
4			
5			

**Inspector Name**

PG - JAYSON

**Inspector Signature**



Collaboration between  & 