



# Vehicle Inspection Checklist

## Date & Time

11/08/2021 10:30 AM

	Fill in the details below
Dealer Name	PANCA ABADI AUTOMOBILE SDN BHD
Dealer Location	Penang
Make/Model	BMW X6 XDrive 401 M Sport
Colour	Metallic Blue
Chassis/Number Plate	WBACY62050LF66272
Year Make	2020
Mileage	6133 kms

## Engine

	Pass
Engine Diagnosis	✓
Engine Start Properly	✓
Engine Idles Properly	✓
Remote Start System	✓
Engine Noise Normal	✓
Engine Oil/Oil Filter	✓
Throttle Condition	✓
Coolant	✓
Oil Leakage	✓
Exhaust Emission	✓

## Transmission

	Pass
Transmission Diagnosis	✓
Gear Shift Quality	✓
Slippage/Jerking	✓

## Cooling System

	Pass
Diagnosis	✓
Coolant Level	✓
Cooling Fans & Motors	✓

## Body/Chassis

	Pass
Free From Major Accident/Body Cut & Joint	✓
Free From Flood Damage	✓
Genuine Chassis & Engine No. (if applicable)	✓

## Other Electricals

	Pass
Electrical Diagnosis	✓
Starter Operation	✓
Ignition System	✓
Battery	✓
Alternator Output	✓
Fuel System Diagnosis	✓
Braking System Diagnosis	✓
Air-conditioning System Diagnosis	✓
Steering Mechanism Diagnosis	✓

Inspector Name

PG - LOH

**Inspector Signature**



Collaboration between  & 