

### **Date & Time** 15/10/2021 12:00 PM

	Fill in the details below
Dealer Name	HUJAN EMAS AUTO SDN BHD
Dealer Location	MRR2
Make/Model	Nissan Navara
Colour	Silver
Chassis/Number Plate	MNTCC4D23Z0012003 / V6737
Year Make	2016
Mileage	85539 kms

# **Engine**

	Pass
Engine Diagnosis	✓
Engine Start Properly	✓
Engine Idles Properly	✓
Remote Start System	✓
Engine Noise Normal	✓
Engine Oil/Oil Filter	<b>✓</b>
Throttle Condition	✓
Coolant	✓
Oil Leakage	✓
Exhaust Emission	<b>✓</b>

## **Transmission**

	Pass
Transmission Diagnosis	<b>✓</b>
Gear Shift Quality	✓
Slippage/Jerking	<b>✓</b>

# **Cooling System**

	Pass
Diagnosis	<b>✓</b>
Coolant Level	✓
Cooling Fans & Motors	<b>✓</b>

# **Body/Chassis**

	Pass
Free From Major Accident/Body Cut & Joint	<b>✓</b>
Free From Flood Damage	<b>✓</b>
Genuine Chassis & Engine No. (if applicable)	<b>✓</b>

### **Other Electricals**

	Pass
Electrical Diagnosis	✓
Starter Operation	<b>✓</b>
Ignition System	✓
Battery	<b>✓</b>
Alternator Output	✓
Fuel System Diagnosis	✓
Braking System Diagnosis	✓
Air-conditioning System Diagnosis	<b>✓</b>
Steering Mechanism Diagnosis	<b>✓</b>

## **Inspection Notes**

	Section	Item	Notes
1		Rear Left Power window.	Not functioning.
2			
3			
4			
5			

**Inspector Name** 

WS - SYAKIR

Inspector Signature

Collaboration between Carlist.my & WARRANTS



