

Vehicle Inspection Checklist

Date & Time

18/09/2021 10:00 AM

	Fill in the details below		
Dealer Name	SOON LEE AUTO SDN BHD		
Dealer Location	Batu Caves		
Make/Model	Honda CR-V		
Colour	Silver		
Chassis/Number Plate	PMHRM1830GD710754 / BNE8872		
Year Make	2015		
Mileage	71337 kms		

Engine

	Pass
Engine Diagnosis	$\overline{\checkmark}$
Engine Start Properly	$\overline{\checkmark}$
Engine Idles Properly	$\overline{\checkmark}$
Remote Start System	$\overline{\checkmark}$
Engine Noise Normal	$\overline{\checkmark}$
Engine Oil/Oil Filter	$\overline{\checkmark}$
Throttle Condition	$\overline{\checkmark}$
Coolant	$\overline{\checkmark}$
Oil Leakage	$\overline{\checkmark}$
Exhaust Emission	$\overline{\checkmark}$

Transmission

	Pass
Transmission Diagnosis	$\overline{\checkmark}$
Gear Shift Quality	$\overline{\checkmark}$
Slippage/Jerking	$\overline{\checkmark}$

Cooling System

	Pass
Diagnosis	$\overline{\checkmark}$
Coolant Level	$\overline{\checkmark}$
Cooling Fans & Motors	$\overline{\checkmark}$

Body/Chassis

	Pass
Free From Major Accident/Body Cut & Joint	$\overline{\checkmark}$
Free From Flood Damage	$\overline{\checkmark}$
Genuine Chassis & Engine No. (if applicable)	$\overline{\checkmark}$

Other Electricals

	Pass
Electrical Diagnosis	$\overline{\checkmark}$
Starter Operation	$\overline{\checkmark}$
Ignition System	$\overline{\checkmark}$
Battery	$\overline{\checkmark}$
Alternator Output	$\overline{\checkmark}$
Fuel System Diagnosis	$\overline{\checkmark}$
Braking System Diagnosis	$\overline{\checkmark}$
Air-conditioning System Diagnosis	$\overline{\checkmark}$
Steering Mechanism Diagnosis	$\overline{\checkmark}$

Inspection Notes

	Section	Item	Notes
1	Other Electricals	Rear Right Power window	not functioning
2			
3			
4			
5			

Inspector Name

WS Aqash

Inspector Signature

Collaboration between Carlist.my & WARRANTY &



