

Vehicle Inspection Checklist

Date & Time

19/05/2021 4:32 PM

| | Fill in the details below |
|----------------------|---------------------------|
| Dealer Name | Emaslink Holding Sdn Bhd |
| Dealer Location | Cheras, Jalan Loke Yew |
| Make/Model | Harrier 2.0 Premium |
| Colour | Pearl White |
| Chassis/Number Plate | 4489(A2960) |
| Year Make | 2018 |
| Mileage | 22500 |

Engine

| | Pass |
|-----------------------|-------------------------|
| Engine Diagnosis | $\overline{\checkmark}$ |
| Engine Start Properly | $\overline{\checkmark}$ |
| Engine Idles Properly | $\overline{\checkmark}$ |
| Remote Start System | $\overline{\checkmark}$ |
| Engine Noise Normal | $\overline{\checkmark}$ |
| Engine Oil/Oil Filter | $\overline{\checkmark}$ |
| Throttle Condition | $\overline{\checkmark}$ |
| Coolant | $\overline{\checkmark}$ |
| Oil Leakage | $\overline{\checkmark}$ |
| Exhaust Emission | $\overline{\checkmark}$ |

Transmission

| | Pass |
|------------------------|-------------------------|
| Transmission Diagnosis | $\overline{\checkmark}$ |
| Gear Shift Quality | $\overline{\checkmark}$ |
| Slippage/Jerking | $\overline{\checkmark}$ |

Cooling System

| | Pass |
|-----------------------|-------------------------|
| Diagnosis | $\overline{\checkmark}$ |
| Coolant Level | $\overline{\checkmark}$ |
| Cooling Fans & Motors | $\overline{\checkmark}$ |

Body/Chassis

| | Pass |
|--|-------------------------|
| Free From Major Accident/Body Cut & Joint | $\overline{\checkmark}$ |
| Free From Flood Damage | $\overline{\checkmark}$ |
| Genuine Chassis & Engine No. (if applicable) | $\overline{\checkmark}$ |

Other Electricals

| | Pass |
|-----------------------------------|-------------------------|
| Electrical Diagnosis | $\overline{\checkmark}$ |
| Starter Operation | $\overline{\checkmark}$ |
| Ignition System | $\overline{\checkmark}$ |
| Battery | $\overline{\checkmark}$ |
| Alternator Output | $\overline{\checkmark}$ |
| Fuel System Diagnosis | $\overline{\checkmark}$ |
| Braking System Diagnosis | $\overline{\checkmark}$ |
| Air-conditioning System Diagnosis | $\overline{\checkmark}$ |
| Steering Mechanism Diagnosis | $\overline{\checkmark}$ |

Inspector Name

Max

Inspector Signature



Collaboration between Carlist.my & WARRANTY



