



Vehicle Inspection Checklist

Date & Time

01/02/2024

2.00 PM

	Fill in the details below
Dealer Name	MAJU GEMILANG MOTOR SDN BHD
Dealer Location	Klang, Selangor
Make/Model	Perodua Myvi 1.3 EZI
Colour	Yellow
Chassis/Number Plate	PM2M602S002147286 / AJP975
Year Make	2013
Mileage	145208 Kms

Engine

	Pass
Engine Diagnosis	✓
Engine Start Properly	✓
Engine Idles Properly	✓
Remote Start System	✓
Engine Noise Normal	✓
Engine Oil/Oil Filter	✓
Throttle Condition	✓
Coolant	✓
Oil Leakage	✓
Exhaust Emission	✓

Transmission

	Pass
Transmission Diagnosis	✓
Gear Shift Quality	✓
Slippage/Jerking	✓

Cooling System

	Pass
Cooling System Diagnosis	✓
Coolant Level	✓
Cooling Fans & Motors	✓

Body/Chassis

	Pass
Free From Major Accident/Body Cut & Joint	✓
Free From Flood Damage	✓
Genuine Chassis & Engine No. (if applicable)	✓

Other Electricals

	Pass
Electrical Diagnosis	✓
Starter Operation	✓
Ignition System	✓
Battery	✓
Alternator Output	✓
Fuel System Diagnosis	✓
Braking System Diagnosis	✓
Air-conditioning System Diagnosis	✓
Steering Mechanism Diagnosis	✓

Inspection Notes

	Section	Item	Notes
1	APPROVED for 1 Year & Unlimited mileage - Carlist Qualified Warranty Plan		
2			
3			
4			
5			

The checks and OBD scans were performed prior to delivery of this vehicle and only represent the condition of the vehicle at the point of time this inspection is carried out. We do not guarantee any physical deterioration or defects which arise after the inspection date. Warranty Smart provides warranty on the covered components listed in the 'Carlist Qualified' warranty program, and within the claim limits as well as terms and conditions stated in the same warranty program. The mileage reported is as per reading on the odometer and we provide no guarantee on the authenticity of the odometer reading.

Inspector Name

WS – FIK

Inspection Enquiries

1300800833 / 0182280133

Warranty Enquiries

1300800833 / 0109698935 / 0182250071

Collaboration between  & 