



Vehicle Inspection Checklist

Date & Time

17/09/2021 10:00 AM

| | Fill in the details below |
|----------------------|------------------------------|
| Dealer Name | AMCAR MOTORS SDN BHD |
| Dealer Location | Lot 11 Sungai Besi AUTOWORLD |
| Make/Model | Subaru XV |
| Colour | White |
| Chassis/Number Plate | PLPGP7KC5DA303052 / AJN3762 |
| Year Make | 2013 |
| Mileage | 80208 kms |

Engine

| | Pass |
|-----------------------|------|
| Engine Diagnosis | ✓ |
| Engine Start Properly | ✓ |
| Engine Idles Properly | ✓ |
| Remote Start System | ✓ |
| Engine Noise Normal | ✓ |
| Engine Oil/Oil Filter | ✓ |
| Throttle Condition | ✓ |
| Coolant | ✓ |
| Oil Leakage | ✓ |
| Exhaust Emission | ✓ |

Transmission

| | Pass |
|------------------------|------|
| Transmission Diagnosis | ✓ |
| Gear Shift Quality | ✓ |
| Slippage/Jerking | ✓ |

Cooling System

| | Pass |
|-----------------------|------|
| Diagnosis | ✓ |
| Coolant Level | ✓ |
| Cooling Fans & Motors | ✓ |

Body/Chassis

| | Pass |
|--|------|
| Free From Major Accident/Body Cut & Joint | ✓ |
| Free From Flood Damage | ✓ |
| Genuine Chassis & Engine No. (if applicable) | ✓ |

Other Electricals

| | Pass |
|-----------------------------------|------|
| Electrical Diagnosis | ✓ |
| Starter Operation | ✓ |
| Ignition System | ✓ |
| Battery | ✓ |
| Alternator Output | ✓ |
| Fuel System Diagnosis | ✓ |
| Braking System Diagnosis | ✓ |
| Air-conditioning System Diagnosis | ✓ |
| Steering Mechanism Diagnosis | ✓ |

Inspection Notes

| | Section | Item | Notes |
|---|-------------------|-----------------------------------|---|
| 1 | Other Electricals | Air-conditioning system diagnosis | Fault code detected - B14A1 sunload sensor circuit low/open |
| 2 | | | |
| 3 | | | |
| 4 | | | |
| 5 | | | |

Inspector Name

WS Aqash

Inspector Signature



Collaboration between  & 