



Vehicle Inspection Checklist

Date & Time

18/10/2021 11:00 AM

	Fill in the details below
Dealer Name	FORWARD UP AUTO
Dealer Location	Johor
Make/Model	Perodua Axia 1.0 SE Hatchback
Colour	Yellow
Chassis/Number Plate	PM2B200S003086878 / VGQ162
Year Make	2015
Mileage	72143 kms

Engine

	Pass
Engine Diagnosis	✓
Engine Start Properly	✓
Engine Idles Properly	✓
Remote Start System	✓
Engine Noise Normal	✓
Engine Oil/Oil Filter	✓
Throttle Condition	✓
Coolant	✓
Oil Leakage	✓
Exhaust Emission	✓

Transmission

	Pass
Transmission Diagnosis	✓
Gear Shift Quality	✓
Slippage/Jerking	✓

Cooling System

	Pass
Diagnosis	✓
Coolant Level	✓
Cooling Fans & Motors	✓

Body/Chassis

	Pass
Free From Major Accident/Body Cut & Joint	✓
Free From Flood Damage	✓
Genuine Chassis & Engine No. (if applicable)	✓

Other Electricals

	Pass
Electrical Diagnosis	✓
Starter Operation	✓
Ignition System	✓
Battery	✓
Alternator Output	✓
Fuel System Diagnosis	✓
Braking System Diagnosis	✓
Air-conditioning System Diagnosis	✓
Steering Mechanism Diagnosis	✓

Inspector Name

SAG JB - ANDY

Inspector Signature



Collaboration between  & 