

Vehicle Inspection Checklist

Date & Time

31/03/2021 12:30 PM

	Fill in the details below
Dealer Name	HST AUTO ENTERPRISE
Dealer Location	Lot 17 Sungai Besi Autoworld
Make/Model	Perodua Alza 1.5 Advanced (A)
Colour	Silver
Chassis/Number Plate	PM2M502G002235236 / VDP8404
Year Make	2015
Mileage	74509 kms

Engine

	Pass
Engine Diagnosis	$\overline{\checkmark}$
Engine Start Properly	$\overline{\checkmark}$
Engine Idles Properly	$\overline{\checkmark}$
Remote Start System	$\overline{\checkmark}$
Engine Noise Normal	$\overline{\checkmark}$
Engine Oil/Oil Filter	$\overline{\checkmark}$
Throttle Condition	$\overline{\checkmark}$
Coolant	$\overline{\checkmark}$
Oil Leakage	$\overline{\checkmark}$
Exhaust Emission	$\overline{\checkmark}$

Transmission

	Pass
Transmission Diagnosis	$\overline{\checkmark}$
Gear Shift Quality	$\overline{\checkmark}$
Slippage/Jerking	$\overline{\checkmark}$

Cooling System

	Pass
Diagnosis	$\overline{\checkmark}$
Coolant Level	$\overline{\checkmark}$
Cooling Fans & Motors	$\overline{\checkmark}$

Body/Chassis

	Pass
Free From Major Accident/Body Cut & Joint	$\overline{\checkmark}$
Free From Flood Damage	$\overline{\checkmark}$
Genuine Chassis & Engine No. (if applicable)	$\overline{\checkmark}$

Other Electricals

	Pass
Electrical Diagnosis	$\overline{\checkmark}$
Starter Operation	$\overline{\checkmark}$
Ignition System	$\overline{\checkmark}$
Battery	$\overline{\checkmark}$
Alternator Output	$\overline{\checkmark}$
Fuel System Diagnosis	$\overline{\checkmark}$
Braking System Diagnosis	$\overline{\checkmark}$
Air-conditioning System Diagnosis	$\overline{\checkmark}$
Steering Mechanism Diagnosis	$\overline{\checkmark}$

Inspector Name

WS Aqashah

Inspector Signature



Collaboration between Carlist.my & WARRANTY SMART





