



Vehicle Inspection Checklist

Date & Time

29/05/2021 1:30 PM

| | Fill in the details below |
|----------------------|--------------------------------|
| Dealer Name | PANCA ABADI AUTOMOBILE SDN BHD |
| Dealer Location | Penang |
| Make/Model | Mercedes E300 Coupe 2.0 |
| Colour | White |
| Chassis/Number Plate | WDD2383482F126457 |
| Year Make | 2019 |
| Mileage | 14361 kms |

Engine

| | Pass |
|-----------------------|------|
| Engine Diagnosis | ✓ |
| Engine Start Properly | ✓ |
| Engine Idles Properly | ✓ |
| Remote Start System | ✓ |
| Engine Noise Normal | ✓ |
| Engine Oil/Oil Filter | ✓ |
| Throttle Condition | ✓ |
| Coolant | ✓ |
| Oil Leakage | ✓ |
| Exhaust Emission | ✓ |

Transmission

| | Pass |
|------------------------|------|
| Transmission Diagnosis | ✓ |
| Gear Shift Quality | ✓ |
| Slippage/Jerking | ✓ |

Cooling System

| | Pass |
|-----------------------|------|
| Diagnosis | ✓ |
| Coolant Level | ✓ |
| Cooling Fans & Motors | ✓ |

Body/Chassis

| | Pass |
|--|------|
| Free From Major Accident/Body Cut & Joint | ✓ |
| Free From Flood Damage | ✓ |
| Genuine Chassis & Engine No. (if applicable) | ✓ |

Other Electricals

| | Pass |
|-----------------------------------|------|
| Electrical Diagnosis | ✓ |
| Starter Operation | ✓ |
| Ignition System | ✓ |
| Battery | ✓ |
| Alternator Output | ✓ |
| Fuel System Diagnosis | ✓ |
| Braking System Diagnosis | ✓ |
| Air-conditioning System Diagnosis | ✓ |
| Steering Mechanism Diagnosis | ✓ |

Inspector Name

G.O.CCY

Inspector Signature



Collaboration between  & 